



Summary

Inspection Details

Exterior (driveway and surrounding)

Garage / Carport

Roof

6

Siding and / or Exterior covering

1

Attic, Insulation & Ventilation

1

Kitchen

Living Room

Living Room 2

Bedroom 1


Bedroom 2

Bedroom 3

Report Tools ▼



1234 Main Street
Greenville, NY 12083
12/15/2025 9:00AM



INSPECTOR
Andrew Ballato



AGENT
Agent Name
Agency Name

Full Report

Summary

Safety Hazard

Share

PDF ▼



Maintenance Item



Recommendation

1 - Inspection Details